

Sizewell C Notice to Mariners No 15 of 2026

Marine Construction Zone Update

Marine Construction Zone Special Mark – Light unreliable

Mariners are advised that a special mark light is unreliable.

The Fl y 5s light on the special mark buoy marking the SE extremity of the Marine Construction Zone (MCZ) has been reported as unreliable – the position of the buoy in question is as below and is indicated on the accompanying chartlet. Mariners should proceed with caution when navigating in this area.

Latitude **Longitude**
52° 12.9263' N 001° 38.2270' E

SZC Harbour Master

Date: 23/03/2026

Notice to Mariners in Force

2024

No.15 of 2024

No. 19 of 2024

2025

No.10 of 2025

2026

No. 6 of 2026

No. 7 of 2026

No. 8 of 2026

No. 11 of 2026

No. 12 of 2026

No. 14 of 2026



Any further enquiries regarding this Notice to Mariners should be directed to:
Harbour.Master@sizewellc.com